ARL-STRUC-TM-550

AR-006-664







# DEPARTMENT OF DEFENCE DEFENCE SCIENCE AND TECHNOLOGY ORGANISATION AERONAUTICAL RESEARCH LABORATORY

**MELBOURNE, VICTORIA** 

DTIC ELECTE JUN 2 2 1992 A

Aircraft Structures Technical Memorandum 550

# FATIGUE TESTING OF A FLOOR ANCHOR SPECIMEN

by

This document has been approved for public release and sale; its distribution is unlimited.

P. PIPERIAS

92-16341

Approved for public release.

© COMMONWEALTH OF AUSTRALIA 1992

MARCH 1992

92 5 1 104

This work is copyright. Apart from any fair dealing for the purpose of study, research, criticism or review, as permitted under the Copyright Act, no part may be reproduced by any process without written permission. Copyright is the responsibility of the Director Publishing and Marketing, AGPS. Enquiries should be directed to the Manager, AGPS Press, Australian Government Publishing Service, GPO Box 84, CANBERRA ACT 2601.

# DEPARTMENT OF DEFENCE DEFENCE SCIENCE AND TECHNOLOGY ORGANISATION AERONAUTICAL RESEARCH LABORATORY

Aircraft Structures Technical Memorandum 550

#### FATIGUE TESTING OF A FLOOR ANCHOR SPECIMEN

		Accusion For
by P. PIPERIAS		OTIS ORAZI D OTIO TAB EI OUT Hounced EI Outstification
SUMMARY		By Duc ibritten/
		Evallability Godes
	24	Clat Avail and for Special
		A-1

The fatigue testing of a floor anchor restrained in concrete is outlined. Aspects of the test and fatigue life are discussed.



© COMMONWEALTH OF AUSTRALIA 1992

**POSTAL ADDRESS:** 

Director, Aeronautical Research Laboratory 506 Lorimer Street, Fishermens Bend 3207 Victoria Australia

# CONTENTS

1. INTRODUCTION	1
2. TEST SPECIMEN	1
3. TEST PROCEDURE	2
4. RESULTS	2
5. DISCUSSION	3
6. CONCLUSIONS	1
7. ACKNOWLEDGEMENTS	4
REFERENCES	
FIGURES 1-12	
APPENDICES A,B	
DISTRIBUTION	

DOCUMENT CONTROL DATA

#### 1. INTRODUCTION

To expand its capabilities and services, Aircraft Structures Division at the Aeronautical Research Laboratory (ARL) Defence Science and Technology Organisation, has constructed a new Structural Test Laboratory (STL) (Fig. 1).

The strong floor slab (Fig. 2) located in the STL incorporates screw-threaded socket anchors (Figs. 3-5) used to restrain static and dynamic loads from test rigs. Threaded studs can be screwed into the sockets and used to clamp rig members to the floor.

The design specification for the building called for a minimum life of 10<sup>9</sup> cycles for each anchor to a maximum tensile load of 10 000 kg force (98 000 N).

Some available data [1,2] for large diameter threaded specimens comparable to the STL floor anchors, indicated that the anchor may not meet the design specification for fatigue life. Those data typically showed fatigue lives of the order of  $10^7$  cycles at alternating stress amplitudes approximately half that specified for the STL floor anchors, but at significantly higher mean stresses (Appendix A). In order to resolve the doubt on the STL floor anchor design cast by the data in References 1 and 2, a fatigue test was conducted on a specimen representative of a 'cast-in' floor anchor.

This paper describes the construction of the specimen and its associated testing up to  $10^8$  cycles.

#### 2. TEST SPECIMEN

The arrangement of the anchors in the strong floor slab is shown in Figure 4. Typical spacing of anchors is 1000 mm. Details of the cast-in anchor are shown in Figure 5. It comprises an internally threaded socket 170mm long, which finishes flush with the surface of the floor. An anchor rod, 900mm long, is screwed into the bottom \$0mm of the socket and penetrates through to the bottom of the 1m thick slab. The stud to anchor rig members then screw into the top 90mm of the socket. All components are of galvanised mild steel and a 36mm metric thread size is used throughout. The floor anchor is not connected to the slab reinforcement but relies on a flange near the base of the anchor rod to hold it in the concrete. The test specimen was fabricated from a spare anchor assembly and surplus materials used in the construction of the strong floor.

Figure 6 shows the floor anchor specimen assembly. To contain the anchor for this test, a mild steel casing was constructed (Fig. 7) into which the anchor and associated reinforcing bars were fitted (Fig. 8). Subsequently, concrete from the same

batch as the strong floor was poured into the specimen assembly. The enclosed area around the anchor was square in cross-section with a side length of 300 mm. The specimen size was limited to a manageable weight and for clearance in the testing machine. The specimen was designed to locally represent the STL floor anchors, surrounding concrete and reinforcement as closely as possible. However, because of a late change to the design of the STL strong floor reinforcement, the reinforcement in the specimen was of lighter gauge but more closely spaced than in the strong floor. Y20 reinforcement rods at 100mm grid pitch were originally specified for the slab, but were changed to Y24 rods at 150mm pitch.

Machined fittings were used to mount the specimen in the testing machine. The general set up is shown in Figure 9.

#### 3. TEST PROCEDURE

A closed-loop servo-controlled hydraulic machine (Appendix B) was used to apply the load cycles. For stability, the specimen was inverted and bolted to the cross-head of the machine (Fig. 10). A steel cable was attached to the casing and testing machine crosshead in order to support the specimen in the event of bolt failure. The load train from the specimen to the actuator was as follows (Fig. 9):

- (i) The anchor stud was connected via an adaptor to the load cell.
- (ii) The load cell was connected via an adaptor and a long slender rod to the actuator.

All links were appropriately secured with locking nuts.

The common universal testing configuration where the specimen is located between the actuator and load cell with universal joints to eliminate bending of the specimen was not adopted here. The joints involved would have incurred excessive pin wear and lubrication problems due to the large number of cycles required for testing. Instead, a long slender connecting rod was used at one end to minimise bending loads and care was taken with the mounting of the specimen to the machine crosshead to achieve good alignment. Because the loading was all tensile, potential buckling of the long load train was not a factor.

A servo-amplifier control system was programmed to produce a constant amplitude sinusoidal loading (0 to 98 kN).

On completion of the fatigue test a static tensile test was conducted to determine the strength of the stud and anchor. The floor anchor specimen was tested to failure in a 2MN MTS machine.

#### 4. RESULTS

Visual inspections were carried out regularly during fatigue cycling in order to detect any deterioration of the specimen and load linkage.

Cycling commenced on the 1/9/87 and one hundred million cycles were completed by 17/10/90. The following is a record of events up until 100 000 000 cycles.

#### At zero cycles:

Cycling commenced.

#### At 169 000 cycles:

Daily inspections revealed no signs of deterioration. It was determined that 1000 cycles were completed in 6.5 minutes, giving a test frequency of 2.6 Hertz.

#### At 1 136 000 cycles:

A detailed inspection was undertaken. The load train was dismantled and a visual inspection of the stud connection was made. Lubricating grease was evident at the rim of the stud socket, this having accumulated under gravity due to the configuration of the specimen. No visible damage to the stud was observed. It was recommended that the test be continued until 10<sup>8</sup> cycles at the prescribed load, at which point a further detailed inspection would be made.

#### At 2 211 000 cycles:

Specks of concrete were collected in the retaining tray. An inspection revealed that a slight amount of concrete spalling was evident. This was not considered critical and testing was continued.

#### At 4 195 000 cycles:

The micro-switch displacement limits were exceeded due to adaptor bolt failure. A new bolt, fitted with spherical seat to improve alignment was used as a replacement and cycling was continued.

#### At 7 312 000 cycles:

Concrete started to chip away around the socket. The concrete chips were 5 to 10 mm long. No apparent damage to the stud was observed and testing continued.

#### At 10,000,000 cycles:

The load chain was dismantled and a detailed inspection of the stud-socket arrangement was made. At some stage after 10 000 000 cycles the stud-socket had separated locally from the concrete. No further damage was observed and testing continued up to  $10^8$  cycles.

#### At 100 000 000 cycles:

Fatigue testing was stopped. Visual inspection revealed no sign of failure or cracking. The static strengths of the stud and anchor were determined. In the first test the stud failed under a tensile load of 417.4kN and elongated by over 20mm. The failure occurred through the thread root just outside the end of the socket. The stud was then replaced with a high tensile steel stud and the test was repeated. This time the anchor rod failed just below the socket, and the socket and a short length of the anchor rod broke out of the concrete, causing significant spalling of the surrounding concrete and exposing the reinforcement rods (Fig. 11). Failure of the anchor rod was recorded at a tensile load of 502kN. The anchor rod elongated approximately 15mm. Both fractures are shown in Figure 12.

#### 5. DISCUSSION

The testing machine operating frequency limit of 2.6Hz meant that it would take a prohibitively long time (40 years) to test the specified life of  $10^9$  cycles. Testing to  $10^8$  cycles followed by a residual strength test was adopted as a compromise. It took just over 3 years to reach the  $10^8$  cycles at full amplitude.

In the residual strength testing, the anchor assembly exhibited good overload protection characteristics, in that the stud failed first. The stud is a removable and readily replaceable component.

#### 6. CONCLUSIONS

The testing to 10<sup>8</sup> cycles and subsequent residual strength testing has not satisfied the design specification for 10<sup>9</sup> cycles, but has demonstrated that the anchors should have adequate life for their general use in the STL. At the end of 10<sup>8</sup> cycles no signs of deterioration affecting the life of the anchor assembly were observed.

The 20% reserve strength of the anchor rod over the stud is a good feature and should be preserved. If high strength steel studs are used, they should be appropriately waisted down so that they fail at a tensile load of approximately 420kN.

#### 7. ACKNOWLEDGEMENTS

The author wishes to acknowledge the contributions made by K. Watters and the Technical officers and Assistants from the Structures Experiment and Instrumentation Groups of Aircraft Structures Division, ARL.

# REFERENCES

- [1] ESDU (Engineering Science Data Unit) 68045 Fatigue strength of large screw threads under axial loading.
- [2] Rowan, R.W., Beckett, R.C., Simpson, R., Static and fatigue tests on prestressing steel bars and couplings, Aeronautical Research Laboratories, Structures and Materials Technical Memorandum 125 (1963).




Fig. 1 Structural Test Laboratory




Fig. 2 Strong Floor



Fig. 3a Grid of Anchor plugs on a portion of the floor in the STL




Fig. 3b Close up of 4 anchors. One with a sealing plug removed



Fig. 3c Sub-floor view of anchors and reinforcement prior to concreting

FIG.4 FLOOR ANCHOR ARRANGEMENT






FIG.6 FLOOR ANCHOR SPECIMEN GENERAL ASSEMBLY.



Fig. 7 Casing of floor anchor specimen




Fig. 8 View looking down on specimen before concrete is poured



Fig. 9 General set-up in testing machine




Fig. 10 Close-up of specimen as mounted up against cross-head




Fig. 11 Floor damage resulting from socket failure




Fig. 12a Stud fracture surface




Fig. 12b Anchor fracture surface

#### APPENDIX A

#### COMPARATIVE DATA

Data from References 1 and 2 are presented here for comparison.

Reference 1 has data on approximately 160 fatigue tests of solid steel bolts and studs with nominal thread diameter equal to or greater than 38 mm. Reference 2 has data on repeated tension fatigue tests carried out on prestressing tendons (32 mm diameter) and couplings.

Although these data are not for an assembly cast in concrete it nevertheless provides a guide to the fatigue life of such a specimen.

From [1]: Values for threads being cut or ground.

Failure at  $10^7$  (5 % scatter) occurred at 28.8 MPa alternating stress.

Mean stress for the range of specimens: 60.8 MPa to 281.2 MPa.

#### From [2]:

Failure at 10<sup>7</sup> cycles occurred at 20.7 MPa alternating stress.

Mean stress for the range of specimens: 414 MPa.

The 'cast-in' floor anchor did not fail after 10<sup>8</sup> cycles at 48.1 MPa alternating stress and a mean stress of 48.1 MPa.

#### Fatigue life

The following is a fatigue calculation for the stud-socket arrangement without the influence of the surrounding concrete. The stresses are plotted on a fatigue diagram (fig. A1).

#### Data:

```
stud diameter of specimen = 36 mm

repeated load range = 0 to 98000 N (tension)

yield stress = 250 MPa (Mild Steel)

ultimate tensile strength (UTS) = 480 MPa (conservative)

endurance limit = 0.5 \times \text{UTS} (typical)

= 0.5 \times 480

= 240 MPa
```

fatigue stress-concentration factor  $K_f = 3.8$  (for cut threads)

#### Calculation:

The mean and alternating loads are:

$$P_m = \frac{P_{max} + P_{min}}{2} = \frac{98000}{2} = 49000 \text{ N}$$

$$P_a = \frac{P_{max} - P_{min}}{2} = \frac{98000}{2} = 49000 \text{ N}$$

stress area = 
$$1018 \text{ mm}^2$$

Thus the mean and alternating stresses are:

$$\sigma_m = \frac{49000}{1018} = 48.1 \text{ MPa}$$

$$K\sigma_a = 3.8 \times \frac{49000}{1018} = 183 \text{ MPa}$$

A plot of the stresses (point A) shown in figure A1 indicates that the stud-socket arrangement is safe.




FIG.A1 FATIGUE DIAGRAM.

#### APPENDIX B

#### MACHINE COMPONENTS FOR FATIGUE TEST

# Load cell properties.

manufacturer: BLH electronics

type : U3G2 serial No. : 83796

capacity : 50.000 lb. (220 kN)

# Actuator properties.

manufacturer: Vickers hydraulics Compact hydraulic (oil) cylinder.

Model No. : V30-FC-NC-H-T-1R-5H

#### **DISTRIBUTION**

#### **AUSTRALIA**

#### Department of Defence

# Defence Central Chief Defence Scientist AS, Science Corporate Management )shared copy FAS Science Policy Director, Departmental Publications Counsellor, Defence Science, London (Doc Data sheet only) Counsellor, Defence Science, Washington (Doc Data sheet only) Scientific Adviser, Defence Central OIC TRS, Defence Central Library Document Exchange Centre, DSTIC (8 copies) Defence Intelligence Organisation Librarian H Block, Victoria Barracks, Melb (Doc Data sheet only) Aeronautical Research Laboratory Director Library Chief Aircraft Structures & Materials Division Author: P. Piperias K.C. Watters D. Graham I. Anderson G. Revill F. Harris R. Boykett R. Kaye R. Parker P. Shaw D. Symons A. Goldman P. Hayes

#### Navy Office

Navy Scientific Adviser (3 copies Doc Data sheet only)

#### Army Office

Scientific Adviser - Army (Doc Data sheet only)

#### Air Force Office

Air Force Scientific Adviser (Doc Data sheet only)

SPARES (6 COPIES)

TOTAL (35 COPIES)

# **DOCUMENT CONTROL DATA**

PAGE CLASSIFICATION	
UNCLASSIFIED	

PRIVACY MARKING

1a. AR NUMBER AR-006-664	1b. ESTABLISHMENT NUMBER ARL-STRUC-TM-550	2. DOCUMENT DATE MARCH 1992		3. TASK NUMBER DST 89/076
4. TITLE FATIGUE TESTI SPECIMEN	NG OF A FLOOR ANCHOR	5. SECURITY CLASSIFIC (PLACE APPROPRIATE CIN BOXIS) IE. SECRET (STRESTRICTED (R), LIMITI UNCLASSIFIED (UI).  U  U  U  DOCUMENT TITLE	LASSIFICATION 6), CONF. (C)	6. NO. PAGES 23 7. NO. REFS.
8. AUTHORISI P. PIPERIAS		9. DOWNGRADING/DEL	IMITING INSTRUCTION	DNS
10. CORPORATE AUTH	OR AND ADDRESS	11. OFFICE/POSITION		
AERONAUTICAL R	ESEARCH LABORATORY	SPONSOR	DSTO	<u> </u>
506 LORIMER STR	EET	SECURITY	-	
FISHERMENS BEN	D VIC 3207	DOWNGRADING		
		·~~QOVAL	CSMD	
	<del></del>	•		
Approved for public release.  OVERSEAS ENQUIRIES OUTSIDE STATED LIMITATIONS SHOULD BE REFERRED THROUGH DISTIC, ADMINISTRATIVE SERVICES BRANCH, DEPARTMENT OF DEFENCE, ANZAC PARK WEST OFFICES, ACT 2601				
13a THIS DOCUMENT	MAY BE ANNOUNCED IN CATALOGUES A	ND AWARENESS SERVICES	AVAILABLE TO	
No Limitations -				
13b. CITATION FOR OTHER PURPOSES (IF CASUAL. ANNOUNCEMENT) MAY BE  X UNRESTRICTED OR  AS FOR 13a.				
14. DESCRIPTORS				15. DISCAT SUBJECT
Fatigue tests Fatigue life				CATEGORIES
Anchors				201101
16. ABSTRACT				1
The fatigue testing of a floor anchor restrained in concrete is outlined. Aspects of the test and fatigue life are discussed.				

PAGE	CLA	SSIFT	CAT	TON
INC	זי 4	22	मा	Fr

PRIVACY MARKING

THIS PAGE IS TO BE USED TO RECORD INFORMATION WHICH IS REQUIRED BY THE ESTABLISHMENT FOR ITS OWN USE BUT WHICH WILL NOT BE ADDED TO THE DISTIS DATA UNLESS SPECIFICALLY REQUESTED.

16. ABSTRACT (CONT).		
17. IMPRINT		
AERONAUTICAL RI	ESEARCH LAE	CORATORY, MELBOURNE
18. DOCUMENT SERIES AND NUMBER	19. COST CODE	20. TYPE OF REPORT AND PERIOD COVERED
Aircraft Structures Technical Memorandum 550	26 207J	
21. COMPUTER PROGRAMS USED		
22. ESTABLISHMENT FILE REF.(S)		
23. ADDITIONAL INFORMATION (AS REQUIRED)	-	